COMPLETION REPORT

1	Name of Work & Job Code	Maintenance of Crematerium Burial Ground and office Maintenance in ward no 13 Shettyhalli Sub Division. 013-19-000010
2	Sanctioned Estimate No & Date (AS No)	BBMP/EE/DD/AS/204/19-20 Dt: 30.01.2020
	Sanctioned Estimate No & Date (TS No)	BBMP/EE/DZ/TS/44/19-20 Dt: 30.01.2020
3	Head Of Account which is Chargable	P-3291
4	Work Order No. & Date	BBMP/DD/WO/19/2020-21 Dt: 21.05.2020
5	Name of Contractor	D. V.Kumar
6	Time Stipulated for completion of work	-
7	Date of Commencement	BBMP/DD/WO/19/2020-21 Dt: 21.05.2020
8	Date of Completion	03.07.2020
9	Delay in execuation of Work	-
10	Measurement recoded in M.B Book No.	M.B No. 4879Pg. 487801-805
11	Check Measurment of the Asst. Executive Engineer	6/7/20
12	Name of the Office/Offical in charge of the Work	
13	a) Assistant Engineer	Venketeshappa
	b) Asst.Executive Engineer	Nagesh Murthy

Sanctioned Estimate Amount	Amount Claims As per Actually Executed as per bills	Excess	Savings
Rs 750,000	₹12293=00	—	37707=00

1) Certified that the above work has been completed within the stipulated time noted in the Work Order.
2) Certified that theContractor has delayed and completed the work for which necessary fine
3) Certified that the above work has been executed by the Contractor satisfactory.

Asst. Engineer

Asst.Executive Engineer
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಬ್ಬಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Executive Engineer
EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Scanned with CamScanner